HUMIDITY TRANSMITTER

Model: TR-HUM1A4 *ISO-9001, CE, IEC1010*









The Art of Measurement

HUMIDITY TRANSMITTER

Model: TR-HUM1A4

Measure Range	10 %RH to 95 %RH
Output	4 - 20 mA
'	
	10 %RH = 5.6 mA
	50 %RH = 12 mA
	95 %RH = 19.2 mA
External	ZERO VR
Adjustment	SPAN VR
Power	90 - 260 ACV
Supply	50 Hz/60 Hz
Operation	0 - 50 ℃
Temperature	32 - 122 °F
Operation	Less than
Humidity	80 %RH
Accessory	Humidity probe
Included	
Optional	33% RH Humidity calibrator,
Accessories	RHA-33A
	75% RH Humidity calibrator,
	RHA-75A
Mounting	Din rail or Wall
Case	ABS plastic
Others	Separate probe with plug

^{*} Appearance and specifications listed in this brochure are subject to change without notice.